

## Possible cause of noise due to incorrect drip tray placement

Correct



Incorrect

